

**Corrigendum on the  
Interpretation Guidelines for Rapid Load Testing on piles**  
by P. Hölscher *et al.*

CRC Press  
available from: <http://www.crcpress.com/product/isbn/9780415695206>

Known errata on 2 February 2012

## **1. Appendix C**

The heading of the second last column in the Tables C2, C3 en C4 reads SLT; This should be RLT

## **2. Appendix F**

The values of the  $\xi_1$  and  $\xi_2$  in the example are based on the Dutch National Annex. In this case, the Eurocode suggests  $\xi_1 = 1.30$  and  $\xi_2 = 1.20$  (Table A.9).

## **3. Section 7.1 Open-ended piles**

page 31: line 7 from bottom:  
the reference "Matsumoto, Muroi et. al., 1998" must be removed